

Patent 7,618,462

PATENT

IN UNITED STATES PATENT AND TRADEMARK OFFICE

Patent No.: 7,618,462

Docket No: STD00.01CIP2CON

Issue Date: November 17, 2009

Patentee: Steven W. Ek

Title SYSTEM AND METHOD FOR JOINT RESURFACE REPAIR

REQUEST FOR CERTIFICATION OF CORRECTION

Attn: Certificate of Correction Branch
Commissioner for Patents
P.O. Box 1450
Alexandria, VA 22313-1450

It is requested that a Certificate of Correction be issued correcting printing errors appearing in the above-identified United States patent. One copy of the text of the Certificate in the suggested form is attached.

Issuance of the Certificate of Correction would neither expand nor contract the scope of the claims as properly allowed, and re-examination is not required.

As the error is that of the Patent Office, it is believed that no fee is due.

Respectfully submitted,

Customer Number: 32047

Tel. 603-668-6560

By /Edmund P. Pfleger/

Edmund P. Pfleger
Reg. No.: 41,252

**UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION**

PATENT NO : 7,618,462

DATED : November 17, 2009

INVENTOR(S) : Steven W. Ek

It is certified that errors appear in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

On the face page, in field (63), in column 1, under "Related U.S. Application Data", line 1, delete "Continuation-in-part" and insert - - Continuation - -, therefor.

On the face page, in column 2, under "Other Publications", line 2, after "Replacement" delete "or" and insert - - of - -, therefor.

MAILING ADDRESS OF SENDER:

Intellevate
P.O. Box 52050
Minneapolis, MN 55402

PATENT NO. 7,618,462

No. of additional copies



Atty Docket No: STD00.01CIP2CON